

```
-- Langmuir Systems  
-- www.langmuirsystems.com
```

```
firstPierceTime = 0 --this is an extra delay added to the first pierce as needed by some machines  
version = 1.6
```

```
local function isEmpty(s)  
    return s == nil or s == ''  
end
```

```
function OnAbout(event)  
    ctrl = event:GetTextCtrl()  
    ctrl:AppendText("Post for CrossFire PRO and CrossFire using FireControl Software\n")  
    ctrl:AppendText("\n")  
    ctrl:AppendText("For CrossFire PRO and CrossFire w/power Z-axis add-on, be sure to set Pierce Height, Plunge Rate,  
and Cut Height values in order to activate IHS sequence. There is a 1 inch rapid retract move after each cut loop by  
default.\n")  
    ctrl:AppendText("\nFor CrossFire without powered Z-axis, Pierce Height and Cut Height must be both set to 0 to disable  
IHS.\n")  
end
```

```
function OnInit()  
    programSpeed = 0 -- variable overridden with fastest cut speed  
    post.SetOptions(post.ARC_SEGMENTS)  
    post.SetCommentChars ("()", "[]") --make sure ( and ) characters do not appear in system text  
    post.Text ("(v".. version .."-sc)\n")  
    post.Text ("G90 G94\n")  
    post.Text ("G17\n")  
    if(scale == metric) then  
        post.Text ("G21 (Units: Metric)\n") --metric mode  
    else  
        post.Text ("G20 (Units: Inches)\n") --inch mode  
    end  
    post.TextDirect ("H0\n") -- thc OFF, Machine in control of Z
```

```
bigArcs = 1 --stitch arc segments together  
minArcSize = 0.05 --arcs smaller than this are converted to moves  
firstPierce = firstPierceTime
```

```
-- post.Text ("G0 Z", (safeZ * scale), "\n") --*****Added Raize Tool Move Z RapidClearance  
-- post.Text ("G4 P0.5\n") -- *****Added Pause
```

```
post.Text ("G38.2 Z-5.0 F50.0\n") -- *****ADDED Auto Zero Down  
post.Text ("G38.4 Z0.5 F20.0\n") -- *****ADDED Auto Zero Up
```

Auto Zero At

Start I may switch this back to manual Zero with above Code Only

```
post.Text ("G92 Z0.0\n") -- *****ADDED Auto Zero Value Set
```

```
post.Text ("G0 Z", (safeZ * scale), "\n") -- *****Added Raize Tool Move Z RapidClearance
```

```
post.Text ("G4 P0.5\n") -- *****Added Pause
```

```
end
```

```
function OnFinish()
```

```
    post.Text ("M5 M30\n")  
    post.Text ("(PS" .. programSpeed .. ")\n")
```

```
end
```

```
function OnRapid()
```

```
    if (math.hypot(endX - currentX, endY - currentY) < 0.001) then return end  
    if(endX > 1e30) then return end  
    post.Text ("G0")  
    post.ModalNumber (" X", endX * scale, "0.0###")  
    post.ModalNumber (" Y", endY * scale, "0.0###")
```

```
    if toolType <= 2 then -- *****ADDED ADDS Z MOVEMENT TO GCODE  
        post.ModalNumber (" Z", endZ * scale, "0.0###") -- *****ADDED ADDS Z MOVEMENT TO GCODE  
    end
```

```
    post.Eol()
```

```
end
```

```
function OnMove()
```

```
    if(currentX ~= endX or currentY ~= endY) then  
        post.Text ("G1")  
        post.ModalNumber (" X", endX * scale, "0.0###")  
        post.ModalNumber (" Y", endY * scale, "0.0###")
```

```
    if toolType <= 2 then -- *****ADDED ADDS Z MOVEMENT TO GCODE  
        post.ModalNumber (" Z", endZ * scale, "0.0###") -- *****ADDED ADDS Z MOVEMENT TO GCODE  
    end
```

```
    post.ModalNumber (" F", feedRate * scale, "0.0###")
```

```
    post.Eol()  
    if(feedRate * scale > programSpeed and leadinType == 0) then  
        programSpeed = feedRate * scale  
    end
```

```
end
```

```
end
```

```

function OnArc()
  if(arcAngle <0) then
    post.Text ("G3")
  else
    post.Text ("G2")
  end
  post.NonModalNumber (" X", endX * scale, "0.0###")
  post.NonModalNumber (" Y", endY * scale, "0.0###")

  if toolType <= 2 then -- ****ADDED ADDS Z MOVEMENT TO GCODE
    post.ModalNumber (" Z", endZ * scale, "0.0###") -- ****ADDED ADDS Z MOVEMENT TO GCODE
  end

  post.Text (" I")
  post.Number ((arcCentreX - currentX) * scale, "0.0###")
  post.Text (" J")
  post.Number ((arcCentreY - currentY) * scale, "0.0###")
  post.ModalNumber (" F", feedRate * scale, "0.0###")
  post.Eol()

  if(feedRate * scale > programSpeed and leadinType == 0) then
    programSpeed = feedRate * scale
  end
end

function OnPenDown()
  post.TextDirect ("\n")
  ihs = pierceHeight ~= 0 and cutHeight ~= 0 --enable IHS if both pierce and cut are non-zero
  if (ihs) then
    post.TextDirect ("G92 Z0.\n") -- reset Z to 0
    post.TextDirect ("G38.2 Z".. post.FormatNumber(-5 * 25.4 * scale, "0.0##") .." F".. post.FormatNumber(100 * 25.4 * scale, "0.0##") .."\n") -- IIHS Fast Down
    post.TextDirect ("G38.4 Z".. post.FormatNumber(0.5 * 25.4 * scale, "0.0##") .." F".. post.FormatNumber(20 * 25.4 * scale, "0.0##") .."\n") -- IIHS Slow Up
    post.TextDirect ("G92 Z"..post.FormatNumber(0, "0.0##") .."\n") -- reset Z to IHS 0
    post.TextDirect ("G0 Z"..post.FormatNumber(0.02 * 25.4 * scale, "0.0##") .." (IHS Backlash)\n") -- reset Z to IHS 0
    post.TextDirect ("G92 Z"..post.FormatNumber(0, "0.0##") .."\n") -- reset Z to IHS 0

    post.TextDirect ("G0 Z"..post.FormatNumber(pierceHeight * scale, "0.0##") .." (Pierce Height)\n") -- Z to Pierce
  end
  -- if toolType <= 2 then -- ****ADDED ADDS Z MOVEMENT TO GCODE Work In progress
  Didn't like how long it took to Route auto Zeroed z Axis Each time it dropped.

  -- post.Text ("G38.2 Z-5.0 F50.0\n") -- ****ADDED Auto Zero Down
  -- post.Text ("G38.4 Z0.5 F20.0\n") -- ****ADDED Auto Zero Up
  -- post.Text ("G92 Z0.0\n") -- ****ADDED Auto Zero Value Set
  -- post.Text ("G0 Z", (safeZ * scale), "\n") -- ****Added Raize Tool Move Z RapidClearance
  -- post.Text ("G4 P0.5\n") -- ****Added Pause
  -- end

  post.Text ("M3\n") -- fire torch

  if toolType <= 2 then -- ****ADDED ADDS Z MOVEMENT TO GCODE
    post.Text ("G1 Z", endZ * scale, " F", plungeRate * scale, "\n") -- *ADDED ADDS Z MOVEMENT TO GCODE Enter Material
    post.Text ("G4 P0.5\n") -- ****Added Pause
  end

  if (pierceDelay + firstPierce > 0.001) then -- pierce delay
    post.Text ("G4 P")
    post.Number (pierceDelay + firstPierce,"0.###")
    firstPierce = 0
    post.Eol()
  end

  if (ihs) then
    post.TextDirect ("G1 Z"..post.FormatNumber(cutHeight * scale, "0.0##") .." F".. post.FormatNumber(plungeRate * scale, "0.0##") .." (Cut Height)\n") -- Z to Cut
  end
  if toolType <= 2 then -- ****ADDED ADDS Z MOVEMENT TO GCODE This turns Off
  Torch Height Control In The Machine
    post.TextDirect ("H0\n") -- thc OFF, Machine in control of Z *****ADDED ADDS Z MOVEMENT TO GCODE Unless Plasma
  tool is being used you dont want any H1 In GCode
    else -- ****ADDED ADDS Z MOVEMENT TO GCODE
      post.TextDirect ("H1\n") -- thc ON, THC in control of Z *****ADDED ADDS Z MOVEMENT TO GCODE
  end -- ****ADDED ADDS Z MOVEMENT TO GCODE

  post.Text ("M5\n")

  if toolType <= 2 then -- ****ADDED

```

```
post.Text ("G4 P0.5\n") -- ****Added Pause
post.Text ("G0 Z", (safeZ * scale), "\n") -- ****Added Raize Tool Move Z RapidClearance
post.Text ("G4 P0.5\n") -- ****Added Pause
end
if (endDelay > 0) then
    post.Text ("G4 P")
    post.Number (endDelay, "0.##")
    post.Eol()
end
if (ihs) then
    post.TextDirect ("G0 Z" .. post.FormatNumber(25.4 * scale, "0.0##") .. "\n") -- Z to rapid height
end
post.CancelModalNumbers()
end

function OnDrill()
    OnRapid()
    OnPenDown()
    endZ = drillZ
    OnMove()
    OnPenUp()
    endZ = safeZ
    OnRapid()
end
```